


1 Prepare Workspace

Assemble Baxter Pedestal

tools needed

27 mm Wrench
Tape Measure

1 Roll out pedestal base




2 Unpack boxes

3 Select pedestal height

Adjustable spacer flips to provide different heights.

Measure worksurface height.

Choose pedestal height using diagrams.



4 Assemble pedestal

Refer to instructions affixed to adjustable spacer to build pedestal.



2 Place Baxter - Open Baxter Crate for instructions

3 Add Grippers - Open Gripper Box for instructions